



## The patient, the physician and the technician

Hasta, doktor ve teknisyen

O. Şahap Atik, M.D.

Department of Orthopedics and Traumatology, Medical Faculty of Gazi University, Ankara, Turkey

*First picture:* Eight years after right total knee arthroplasty, the patient requested the same surgery for the left knee. But, she had revision surgery for the right knee for the broken insert.

*Middle picture:* The hand and arm of the doctor holding the patient's leg during radiographic examination for the ankle fracture were also exposed to X-ray.

*Last picture:* The radiograms of both arms of the patient were taken after reduction and casting the forearm fracture. But, the technician included the patient's skull and anterior part of the body in the radiogram.

A patient who does not know what her main problem is; a doctor who does not take care of himself; a technician who does not protect his patient from unnecessary X-ray exposure.

**No comment!**

*İlk resim:* Sağ total diz artroplastisinden sekiz yıl sonra hasta sol dizine aynı ameliyatı yaptırmaya talebinde bulunmuş. Fakat, insert kırıldığı için sağ dize revizyon ameliyatı uygulanmış.

*Ortadaki resim:* Hastanın ayak bileğindeki kırık için röntgen çekimi sırasında bacağı tutan doktorun eli ve kolu da X-ışınına maruz kalmış.

*Sondaki resim:* Önkol kırığı nedeniyle redüksiyon ve alçı yapılan hastanın her iki kolunun da kontrol röntgeni çekilmiş. Ama teknisyen hastanın kafatasını ve vücudunun ön kısmını da röntgen alanına dahil etmiş.

Asıl sorununun ne olduğunu bilmeyen bir hasta, kendini korumayan bir doktor, hastasını gereksiz röntgen ışınına maruz kalmadan korumayan teknisyen.

**Yorum yok!**



Figure 1.



Figure 2.



Figure 3.